

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Assistant Engineer)
(Ref: G.O. Ms. 20/70/PWD dt. 23/01/1970)

1. Name of the Officer : **BASIL MATHAI**
2. Name of the School : **Ilahia Public School, Muvattupuzha**
3. Location with name of Education District / Sub. District : **Muvattupuzha**
4. Classification of Building as specified in column 4 of the application for fitness certificate and size : **RCC Structure with 2 Blocks**

<u>Block 1</u>	<u>Block 2</u>
Porch - 6.10×6.00×3.60	- 1×6.24×6.20×3.60
Class room - 12×6.00×6.00×3.60	Lobby - 12.60×8.80×3.60
Staff room - 2×2.90×6.00×3.60	Office - 7.44×7.26×3.60
Vice principal - 2.90×6.00×3.60	Office - 6.84×7.97×3.60
Lobby - 6.00×6.00×3.60	Room - 7.44×6.00×3.60
FF - 14×6.00×6.00×3.60	Room - 5.66×3.77×3.60
- 1×6.00×2.90×3.60	- 15.08×8.86×3.60
SF - 12×6.00×6.00×3.60	- 3.63×4.79×3.60
- 1×15.30×6.00×3.60	- 7.66×3.80×3.60
TF - 2×6.00×6.00×3.60	- 7.66×3.80×3.60
- 1×24.60×6.00×3.60	Room - 2×6.56×7.97×3.60
SF Lab - 7.44×9.93×3.60	Room - 1×6.97×8.06×3.60
- 7.44×8.06×3.60	FF - 7.44×9.93×3.60
- 7.41×8.06×3.60	Class room - 7.44×3.93×3.60
- 7.66×8.06×3.60	- 7.44×8.06×3.60
- 6.10×6.52×3.60	- 7.41×8.06×3.60
- 2.46×3.40×3.60	- 7.66×8.06×3.60
- 1×6.56×7.97×3.60	- 6.10×6.52×3.60
- 1×6.84×7.97×3.60	- 2.46×3.40×3.60
- 1×7.26×7.44×3.60	- 2×6.56×7.97×3.60
	- 1×6.84×7.97×3.60
	- 1×7.26×7.44×3.60
5. Period for which the certificate is issued : **2026-2027**
6. Nature of defects, if any :
 - a. Foundation and basement
 - b. Superstructure
 - c. Doors and Windows
 - d. Wood work wrought and put up : **Nil**
 - e. Roof
 - f. Flooring
 - g. Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner : **No**
8. Whether maintenance works have been done properly : **Yes**
9. Whether the structure is sound or not for conducting classes : **Sound under normal wind and weather conditions only**

CERTIFICATE

Certified that the building of Ilahia Public School, Muvattupuzha was inspected by me on 16/06/2026 and found to be fit to conduct classes for the period 2026-2027 under the following conditions for the reasons stated above.

- The structure is sound under normal wind and weather conditions only.
- Revised checklist for school fitness (as per order no. GEDN-M1/188/2025-G.EDN dt. 13/05/2026 of General Education (M) Department - Annexure A - Checklist item - Sl. No. 9 regarding electrical wiring safety to be examined by an approved/licensed wireman within one month.
- Revised checklist for school fitness (as per order no. GEDN-M1/188/2025-G.EDN dt. 13/05/2026 of General Education (M) Department - Annexure A - Checklist item - Sl. No. 11 - verification of KMBR provision only is done.
- This certificate is issued considering the civil structural aspect of the building only and the school authorities should strictly follow the directions in circular no. M3/347/2019-HEALTH dt. 09/11/2025 of Health and Family Welfare Department before the commencement of classes.
- School authorities should take steps to update the school building assessment area in the Municipal records before the commencement of classes.

Place: Muvattupuzha

Date: 17/06/2026




Assistant Engineer
LSGD
Muvattupuzha Municipality